

TECHNICAL SERVICE BULLETIN

2024-019



Date Issued: July 31, 2024

Subject: VALIDATE® CM2 402re Lot 10706714 Kit Box Label Adhesion

Explanation: This bulletin is to make customers aware that some users who have recently received a shipment of VALIDATE® CM2 402re lot 10706714 may experience the label falling off during shipment of the kit due to poor adhesive.

This kit is readily identifiable by the inner lot components which are labeled as follows:

CM2 Set, Levels 1 through 5 have Lot 10706709
Tnl set, Levels 1 through 5 have Lot 10706713

Below is an image of the label that should be on the outside of the kit. If you would prefer, we can also send a replacement label that can be attached to the kit box. Please contact Technical Support through phone or email to request a replacement label.



Contact Information: Technical Support Department
LGC Clinical Diagnostics, Inc.
221 US Route 1
Cumberland Foreside, ME 04110
Phone: 1-800-377-9684
+1-207-892-1300
Fax: +1-207-892-2266
E-mail: msc.techsupport@LGCGroup.com